

ATLANTIC HOUSE										
Controle branddeuren noodtrappen										
It	deur	Id.			tal	Lokatie	Nagezien op	Techn.	Opmerking	RF
		orie.	verd.	nr.						
1	BD	N	K	1		13/07/2019	JDS	ok		
2	BD	N	K	2		13/07/2019	JDS	ok		
3	BD	Z	K	3		13/07/2019	JDS	ok		
4	BD	Z	K	4		13/07/2019	JDS	ok		
5	BD	Z	K	5		13/07/2019	JDS	ok		
6	BD	Z	K	6		13/07/2019	JDS	ok		
7	BD	Z	K	7		13/07/2019	JDS	ok		
8	BD	Z	K	8		13/07/2019	JDS	ok		
9	BD	N	0	1		13/07/2019	JDS	ok		
10	BD	N	0	2		13/07/2019	JDS	ok		
11	BD	Z	0	3		13/07/2019	JDS	ok		
12	BD	Z	0	4		13/07/2019	JDS	ok		
13	BD	Z	0	5		13/07/2019	JDS	ok		
14	BD	N	01	1		13/07/2019	JDS	ok		
15	BD	N	01	2		13/07/2019	JDS	ok		
16	BD	Z	01	3		13/07/2019	JDS	ok		
17	BD	Z	01	4		13/07/2019	JDS	ok		
18	BD	Z	01	5		13/07/2019	JDS	ok		
19	BD	N	1	1		13/07/2019	JDS	ok		
20	BD	N	1	2		13/07/2019	JDS	ok		
21	BD	Z	1	3		13/07/2019	JDS	ok		
22	BD	Z	1	4		13/07/2019	JDS	ok		
23	BD	Z	1	5		13/07/2019	JDS	ok		
24	BD	N	2	1		13/07/2019	JDS	ok		
25	BD	N	2	2		13/07/2019	JDS	ok		
26	BD	Z	2	3		13/07/2019	JDS	ok		
27	BD	Z	2	4		13/07/2019	JDS	ok		
28	BD	Z	2	5		13/07/2019	JDS	ok		
29	BD	N	3	1		13/07/2019	JDS	ok		
30	BD	N	3	2		13/07/2019	JDS	ok		
31	BD	Z	3	3		13/07/2019	JDS	ok		
32	BD	Z	3	4		13/07/2019	JDS	ok		
33	BD	Z	3	5		13/07/2019	JDS	ok		
34	BD	N	4	1		13/07/2019	JDS	ok		
35	BD	N	4	2		13/07/2019	JDS	ok		
36	BD	Z	4	3		13/07/2019	JDS	ok		
37	BD	Z	4	4		13/07/2019	JDS	ok		
38	BD	Z	4	5		13/07/2019	JDS	ok		
39	BD	N	5	1		13/07/2019	JDS	ok		
40	BD	N	5	2		13/07/2019	JDS	ok		
41	BD	Z	5	3		13/07/2019	JDS	ok		
42	BD	Z	5	4		13/07/2019	JDS	ok		
43	BD	Z	5	5		13/07/2019	JDS	ok		
44	BD	N	6	1		13/07/2019	JDS	ok		
45	BD	N	6	2		13/07/2019	JDS	ok		
46	BD	Z	6	3		13/07/2019	JDS	ok		
47	BD	Z	6	4		13/07/2019	JDS	ok		
48	BD	Z	6	5		13/07/2019	JDS	ok		
49	BD	N	7	1		13/07/2019	JDS	ok		
50	BD	N	7	2		13/07/2019	JDS	ok		
51	BD	Z	7	3		13/07/2019	JDS	ok		
52	BD	Z	7	4		13/07/2019	JDS	ok		
53	BD	Z	7	5		13/07/2019	JDS	ok		
54	BD	N	8	1		13/07/2019	JDS	ok		
55	BD	N	8	2		13/07/2019	JDS	ok		
56	BD	Z	8	3		13/07/2019	JDS	ok		
57	BD	Z	8	4		13/07/2019	JDS	ok		
58	BD	Z	8	5		13/07/2019	JDS	ok		
59	BD	N	9	1		13/07/2019	JDS	ok		
60	BD	N	9	2		13/07/2019	JDS	ok		

ATLANTIC HOUSE										
Controle branddeuren noodtrappen										
It	Id.					Lokatie	Nagezien op	Techn.	Opmerking	RF
	deur	orie.	verd.	nr.	tal					
61	BD	Z	9	3			13/07/2019	JDS	ok	
62	BD	Z	9	4			13/07/2019	JDS	ok	
63	BD	Z	9	5			13/07/2019	JDS	ok	
64	BD	N	10	1			13/07/2019	JDS	ok	
65	BD	N	10	2			13/07/2019	JDS	ok	
66	BD	Z	10	3			13/07/2019	JDS	ok	
67	BD	Z	10	4			13/07/2019	JDS	ok	
68	BD	Z	10	5			13/07/2019	JDS	ok	
69	BD	N	11	1			13/07/2019	JDS	ok	
70	BD	N	11	2			13/07/2019	JDS	ok	
71	BD	Z	11	3			13/07/2019	JDS	ok	
72	BD	Z	11	4			13/07/2019	JDS	ok	
73	BD	Z	11	5			13/07/2019	JDS	ok	
74	BD	N	12	1			13/07/2019	JDS	ok	
75	BD	N	12	2			13/07/2019	JDS	ok	
76	BD	Z	12	3			13/07/2019	JDS	ok	
77	BD	Z	12	4			13/07/2019	JDS	ok	
78	BD	Z	12	5			13/07/2019	JDS	ok	
79	BD	N	13	1			13/07/2019	JDS	ok	
80	BD	N	13	2			13/07/2019	JDS	ok	
81	BD	Z	13	3			13/07/2019	JDS	ok	
82	BD	Z	13	4			13/07/2019	JDS	ok	
83	BD	Z	13	5			13/07/2019	JDS	ok	
84	BD	N	14	1			13/07/2019	JDS	ok	
85	BD	N	14	2			13/07/2019	JDS	ok	
86	BD	Z	14	3			13/07/2019	JDS	ok	
87	BD	Z	14	4			13/07/2019	JDS	ok	
81	BD	Z	14	5			13/07/2019	JDS	ok	
82	BD	N	15	1			13/07/2019	JDS	ok	
83	BD	N	15	2			13/07/2019	JDS	ok	
84	BD	Z	15	3			13/07/2019	JDS	ok	
85	BD	Z	15	4			13/07/2019	JDS	ok	
86	BD	Z	15	5			13/07/2019	JDS	ok	
87										
88										
89										
90										
84										

nazicht, eventueel smeren, vastzetten scharnieren
 nazicht, eventueel smeren, vastzetten slot met beslag
 controle label branddeur
 nazicht deurdichting
 nazicht, eventueel smeren, vastzetten, afregelen deurpomp
 nazicht sluiting van deur
 controle of de deur nergens sleept of gehinderd wordt.